



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

Michael O. Leavitt
Governor

Robert L. Morgan
Executive Director

Lowell P. Braxton
Division Director

September 11, 2002

CERTIFIED RETURN RECEIPT

7099 3400 0016 8895 6504

Mr. Ken George
Holcium (US) Inc.
6055 East Croydon Road
Auxiliary Route #3
Morgan, Utah 84050

Re: Five-Year Review of Reclamation Surety Estimate, Holcium (US) Inc, Poverty Point Quarry, M/045/012, Tooele County, Utah

Dear Mr. George:

The Division performs periodic reviews of reclamation surety estimates to verify their accuracy. We make adjustments for escalation and any site modifications that may require a change in the amount of reclamation surety presently being held for the site. Division policy requires that reclamation surety estimates being held by the Minerals Reclamation Program include a five year escalation component. The surety estimates are to be reevaluated every five years.

Our records indicate that the reclamation surety estimate for Holcium (US) Inc.'s Poverty Point Quarry is due for review in 2002. To assist us in our review of this cost estimate, we request an updated map of your mine site showing current surface facilities and all mining related disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, ditches, canals, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, evaporation ponds, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

Page 2
Ken George
M/045/012
September 11, 2002

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the mine facilities and disturbed area map, clearly identifying these reclaimed areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Please provide this information within the next 60 days or no later than November 12, 2002. If you are unable to provide this information in this time frame, please contact the Division with justification for requesting additional time. Thank you for providing this information to assist us in completing the upcoming surety estimate review. If you have any questions concerning this reclamation surety review, please contact Doug Jensen at (801) 538-5382.

Sincerely,

A handwritten signature in black ink, appearing to read "D. Wayne Hedberg". The signature is fluid and cursive, with the first name "D." and last name "Hedberg" clearly distinguishable.

D. Wayne Hedberg
Permit Supervisor
Minerals Regulatory Program

sm

cc: John Blake, SITLA
Doug Jensen, DOGM

P:\GROUPS\MINERALS\WP\M045-Tooele\M0450012 Poverty Point\Final\M45-12-bnd-rvw.doc